

1/2

FIG. 1 -




FIG. 2 -

LET E3 = 3						
E2						
E1		2.6	2.7	2.8	2.9	3
2.3		34.12	35.04	35.96	36.88	37.8
2.4		35.56	36.52	37.48	38.44	39.4
2.5		37	38	39	40	41
2.6		38.44	39.48	40.52	41.56	42.6
2.7		39.88	40.96	42.04	43.12	44.2
2.8		41.32	42.44	43.56	44.68	45.8
2.9		42.76	43.92	45.08	46.24	47.4
3		44.2	45.4	46.6	47.8	49

FIG. 3

